


BCM lost communication with base station





Overview

In summary, the U0140 trouble code signifies a loss of communication between your car's main computer and the BCM, often caused by wiring issues, faulty connectors, or a defective module.



BCM lost communication with base station



[U2301 - Lost Communication with the Body Control Module \(BCM\).](#)

Feb 15, 2025 · The OBDII code U2301 indicates that there is a communication failure between the vehicle's control module and the Body Control Module (BCM), which may affect various ...

[DTC No. U214F-57 Lost Communication With BCM](#)

Sep 2, 2022 · DTC No. U214F-57 Lost Communication With BCM DTC No. U234F-57 CAN comm err (BCM) DTC No. U244F-57 CAN comm err (BCM) ...



[U0140 Trouble Code: Meaning, Symptoms, Causes & Fixes](#)

May 23, 2024 · The U0140 trouble code technically means "Lost Communication With Body Control Module (BCM)". Here's exactly what you need to do to fix it.

[U0140 Lost communication with body control ...](#)

Communication errors between modules can lead to malfunctioning systems in the vehicle, impacting both safety and driving comfort. Therefore, ...



[5G Base Station Dielectric Filter Market to ...](#)

2 days ago · The 5G base station dielectric filter market offers key opportunities in expanding 5G networks, IoT growth, smart cities, and ...



[U0140 Code - What Does It Mean & How To Fix It](#)

Dec 1, 2025 · This is one of the most frequent OBD2 trouble codes. Read the full article below to know what it means, how to fix it, and what other codes may show related to it. Definition ...



[U0140 Trouble Code: Meaning, Symptoms, ...](#)

May 23, 2024 · The U0140 trouble code technically means "Lost Communication With Body Control Module (BCM)". Here's exactly what ...





[U1064 Code Meaning, Causes, Symptoms & Tech Notes](#)

Code U1064 Description The U1064 code indicates that the engine control module (ECM) has lost communication with the body control module (BCM) in the vehicle. The BCM is responsible for ...



[Lost communication with TCM and BCM. Please help!](#)

May 18, 2024 · Which are: U0140 - Lost communication with BCM U1110 - Lost Vehicle Speed Message U1120 - Lost Wheel Distance Message U11BC - Lost Brake Switch Message U0101 - ...

[Lost communication with TCM and BCM.](#)

May 18, 2024 · Which are: U0140 - Lost communication with BCM U1110 - Lost Vehicle Speed Message U1120 - Lost Wheel Distance Message ...



[Bluetooth Not Waking Base Stations](#)

Apr 20, 2020 · This prevents waking up Base Stations (1.0) and it disconnects my phone from Viveport. The work around is relatively simple. All I do is go into Device Manager, disable and ...



[2013 BCM possibly not communicating , GM Volt Forum](#)

Oct 21, 2024 · Lost Communication With Body Control Module Performance - Signal Invalid; Lost Communication With Body Control Module Invalid Data; Lost Communication With Body ...



[U0140 Code - What Does It Mean & How To ...](#)

Dec 1, 2025 · This is one of the most frequent OBD2 trouble codes. Read the full article below to know what it means, how to fix it, and what other ...

[U013E - Lost Communication with Body Control Module \(BCM...](#)

The OBDII code U013E indicates that there is a loss of communication with the Body Control Module (BCM) 'A', which may affect various electrical systems in the vehicle.



U0140 - OBD ADVISOR

What Does The U0140 Code Mean? The body control module (BCM) is an electronic module that is part of the vehicle's entire electrical system and it controls functions including but not limited ...



[U0140 Lost communication with body control module BCM](#)

Communication errors between modules can lead to malfunctioning systems in the vehicle, impacting both safety and driving comfort. Therefore, addressing this issue is crucial to ensure ...



Contact Us

For catalog requests, pricing, or partnerships, please visit:
<https://llsolarenergy.co.za>

Scan QR Code for More Information



<https://llsolarenergy.co.za>